

LibDriveIO

supported - original vendor firmware (MTK19XX): 82 firmware(s):

```
ASUS-BW-16D1H-U-A201-W000000-211601141358
ASUS-BW-16D1HT-3.00-W004504-211508101633
ASUS-BW-16D1HT-3.00-W006706-211511031110
ASUS-BW-16D1HT-3.01-W000800-211703311426
ASUS-BW-16D1HT-3.02-W000800-211711241413
HL-DT-ST-BD-RE_BE16NU50-1.00-N000800-211603171336
HL-DT-ST-BD-RE_BE16NU50-1.01-N000900-211606090920
HL-DT-ST-BD-RE_BE16NU50-1.01-N001101-211703130907
HL-DT-ST-BD-RE_BH14NS58-1.00-N004204-211512221504
HL-DT-ST-BD-RE_BH14NS58-1.00-N005405-211703101612
HL-DT-ST-BD-RE_BH16NS40-NS50-1.00-N002502-211508191146
HL-DT-ST-BD-RE_BH16NS40-NS50-1.01-N000500-211511051001
HL-DT-ST-BD-RE_BH16NS40-NS50-1.02-N000200-211512111436
HL-DT-ST-BD-RE_BH16NS40-NS50-1.02-N001901-211703101637
HL-DT-ST-BD-RE_BH16NS50-1.00-N000500-211512230930
HL-DT-ST-BD-RE_BH16NS55-1.00-N000600-211508191151
HL-DT-ST-BD-RE_BH16NS55-1.01-N000500-211511051004
HL-DT-ST-BD-RE_BH16NS55-1.02-N000200-211512111440
HL-DT-ST-BD-RE_BH16NS55-1.02-N001901-211703101630
HL-DT-ST-BD-RE_BH16NS58-1.00-N002302-211512071657
HL-DT-ST-BD-RE_BH16NS58-1.00-N006206-211512221501
HL-DT-ST-BD-RE_BH40N-A1B0-D014214-211510131446
HL-DT-ST-BD-RE_BH40N-A1B0-D015815-211703101705
HL-DT-ST-BD-RE_BP40N-GP01-V001701-211504221450
HL-DT-ST-BD-RE_BP50NB40-1.00-N002602-211409031732
HL-DT-ST-BD-RE_BP50NB40-1.00-N004304-211412161016
HL-DT-ST-BD-RE_BP50NB40-1.00-N005505-211504221517
HL-DT-ST-BD-RE_BP50NB40-NB50-1.00-N000900-211609091048
HL-DT-ST-BD-RE_BP50NB40-NB50-1.00-N002802-211702151837
HL-DT-ST-BD-RE_BP55EB40-1.00-N001501-211504221534
HL-DT-ST-BD-RE_BP55EB40-NB50-1.00-N000700-211701030941
HL-DT-ST-BD-RE_BP55EB40-NB50-1.00-N002802-211702151828
HL-DT-ST-BD-RE_BU10N-GS01-V001701-211305020921
HL-DT-ST-BD-RE_BU20N-1.00-G002202-211405090917
HL-DT-ST-BD-RE_BU20N-1.00-G004504-211412160950
HL-DT-ST-BD-RE_BU20N-1.00-G005705-211504221429
HL-DT-ST-BD-RE_BU20N-1.00-N005305-211504211939
HL-DT-ST-BD-RE_BU20N-A100-D00D60D-211507301534
HL-DT-ST-BD-RE_BU20N-A101-D000100-211602241144
HL-DT-ST-BD-RE_BU20N-EB02-C000400-211610101049
HL-DT-ST-BD-RE_BU20N-EB02-C000900-211412181002
HL-DT-ST-BD-RE_BU20N-T.02-V001301-211405091428
```

```

HL-DT-ST-BD-RE_BU30N-BU30-0217-N000700-211603081656
HL-DT-ST-BD-RE_BU40N-1.00-N003103-211612201528
HL-DT-ST-BD-RE_BU40N-1.00-R002202-211609090954
HL-DT-ST-BD-RE_BU40N-1.00-R004504-211703231903
HL-DT-ST-BD-RE_BU40N-1.01-N000000-211706291017
HL-DT-ST-BD-RE_BU40N-A100-D031531-211608041137
HL-DT-ST-BD-RE_BU40N-A100-D032232-211701021159
HL-DT-ST-BD-RE_BU40N-A101-D000700-211703131630
HL-DT-ST-BD-RE_BU40N-BU10-0002602-211701060941
HL-DT-ST-BD-RE_BU40N-BU10-0003703-211705301728
HL-DT-ST-BD-RE_BU40N-FR07-J001101-211612201651
HL-DT-ST-BD-RE_BU40N-T.00-V003403-211606241658
HL-DT-ST-BD-RE_BU50N-0420-N000000-211605241901
HL-DT-ST-BD-RE_BU50N-AS00-U008408-211607291602
HL-DT-ST-BD-RE_BU50N-AS00-U00B50B-211608041424
HL-DT-ST-BD-RE_BU50N-CC01-V000700-211706280934
HL-DT-ST-BD-RE_BU50N-CCT2-V000700-211703071420
HL-DT-ST-BD-RE_BU50N-CCT5-V000700-211705182023
HL-DT-ST-BD-RE_BU50N-GE02-V000700-211705182030
HL-DT-ST-BD-RE_WH14NS40-NS50-1.00-N001401-211508180940
HL-DT-ST-BD-RE_WH14NS40-NS50-1.01-N000500-211511050956
HL-DT-ST-BD-RE_WH14NS40-NS50-1.02-N000100-211512111503
HL-DT-ST-BD-RE_WH14NS40-NS50-1.02-N001401-211703101655
HL-DT-ST-BD-RE_WH16NS40-NS50-1.00-N001401-211508180932
HL-DT-ST-BD-RE_WH16NS40-NS50-1.02-N000100-211512111459
HL-DT-ST-BD-RE_WH16NS40-NS50-1.02-N001401-211703101650
HL-DT-ST-BD-RE_WH16NS58-TST5-N000900-211708221604
HL-DT-ST-BD-RE_WH16NS60-1.00-N000500-211704251756
HL-DT-ST-BD-RE_WP50NB40-1.00-N000400-211502161437
HL-DT-ST-BD-RE_WP50NB40-1.00-N001501-211504221546
HL-DT-ST-BD-RE_WP50NB40-NB50-1.00-N000800-211701031453
HL-DT-ST-BD-RE_WP50NB40-NB50-1.00-N002802-211702151823
hp-BD-RE_BU20N-BU24-P005005-211504221344
hp-BDRW_BU20N-BW20-P017417-211412160945
hp-BDRW_BU20N-BW20-P018518-211504221413
hp_HLDS-BDRE_BU40N-BW40-P01C01C-211608101011
hp_HLDS-BDRE_BU40N-BW41-P000200-211608161528
hp_HLDS-BDRE_BU40N-BW41-P001101-211612220920
hp_HLDS-BDRE_BU50N-BW50-P01C01C-211608101014
hp_HLDS-BDRE_BU50N-BW50-P01D11D-211612221052

```

supported - original vendor firmware (Pioneer RS): 383 firmware(s):

```

PIONEER-BD-RW_BDR-XS05WF-1.41-B6BE50FD-8221ID25-20140402
PIONEER-BD-RW_BDR-XS05WF-1.42-52FCD13D-8221ID25-20230328
PIONEER-BD-RW__BDR-TD05D-1.00-8F727193-8211ID84-20120713
PIONEER-BD-RW__BDR-TD05-1.00-DCD80C11-8211ID01-20120713
PIONEER-BD-RW__BDR-TD05-1.01-2F9E9D05-8211-20130409
PIONEER-BD-RW__BDR-TD05-1.02-F9240B3B-8211-20140619
PIONEER-BD-RW__BDR-TD05-2.00-5685B301-8211ID72-20120810

```

PIONEER-BD-RW__BDR-XD05-1.10-D128E715-8231-20130424
PIONEER-BD-RW__BDR-XD05-1.20-B4E69320-8231ID69-20131111
PIONEER-BD-RW__BDR-XD05-1.20-F4216DE2-8231-20131115
PIONEER-BD-RW__BDR-XD05-1.21-2D22701B-8231-20140402
PIONEER-BD-RW__BDR-XD05-1.21-9D827504-8231ID69-20140402
PIONEER-BD-RW__BDR-XD05-2.00-D0361B05-8231ID32-20140708
PIONEER-BD-RW__BDR-XD05-2.10-F235B209-8232ID32-20170622
PIONEER-BD-RW__BDR-XD05-3.00-65519583-8231ID34-20140730
PIONEER-BD-RW__BDR-XD05-3.01-5FB5DFEE-8231ID34-20141226
PIONEER-BD-RW__BDR-XD05-3.10-1D3C06AA-8232ID35-20170622
PIONEER-BD-RW__BDR-XD05-3.10-F3AA96E0-8232ID34-20170622
PIONEER-BD-RW__BDR-XD05-3.11-19D6487B-8232ID34-20230303
PIONEER-BD-RW__BDR-XS05-1.10-6BD7E393-8221-20130627
PIONEER-BD-RW__BDR-XS05-1.41-458975F0-8221ID69-20140402
PIONEER-BD-RW__BDR-XS05-1.41-94681536-8221-20140402
PIONEER-BD-RW__BDR-XS05-1.42-FC8D2C2B-8221ID69-20230307
PIONEER-BD-RW__BDR-208-1.40-3D1502C6-8301ID81-20140306
PIONEER-BD-RW__BDR-208-1.50-7BDE40E4-8301ID81-20150924
PIONEER-BD-RW__BDR-208D-1.10-C35BFB0B-8301ID61-20120822
PIONEER-BD-RW__BDR-208D-1.40-79FD6F6F-8301ID61-20140306
PIONEER-BD-RW__BDR-208D-1.50-100E7E06-8301ID61-20150924
PIONEER-BD-RW__BDR-208M-1.10-0F0A2D45-8301-20120822
PIONEER-BD-RW__BDR-208M-1.10-8740B0FB-8301ID60-20120822
PIONEER-BD-RW__BDR-208M-1.10-BAD6EC01-8301ID58-20120822
PIONEER-BD-RW__BDR-208M-1.40-83BE4C7D-8301-20140306
PIONEER-BD-RW__BDR-208M-1.40-B0091F61-8301ID60-20140306
PIONEER-BD-RW__BDR-208M-1.40-E6EF5E2A-8301ID58-20140306
PIONEER-BD-RW__BDR-208M-1.50-1FBF1A91-8301-20150924
PIONEER-BD-RW__BDR-208M-1.50-29298241-8301ID60-20150924
PIONEER-BD-RW__BDR-208M-1.50-52C83D93-8301ID58-20150924
PIONEER-BD-RW__BDR-208M-1.51-836BAB51-8301ID60-20230227
PIONEER-BD-RW__BDR-208M-1.51-9390794C-8301ID58-20230227
PIONEER-BD-RW__BDR-S08-1.10-4514FEB6-8301ID43-20120828
PIONEER-BD-RW__BDR-S08-1.30-E47AEF8C-8301ID43-20130708
PIONEER-BD-RW__BDR-S08-1.40-7B710936-8301ID43-20140306
PIONEER-BD-RW__BDR-S08-1.50-5163944A-8301ID43-20150924
PIONEER-BD-RW__BDR-S08-1.51-9F6F9C71-8301ID43-20230227
PIONEER-BD-RW__BDR-XD05-1.22-1956B79A-8231ID69-20230302
PIONEER-BD-RW__BDR-XD05-2.11-C2A2EDAC-8232ID32-20230303
PIONEER-BD-RW__BDR-XD05-3.11-C3C882FD-8232ID35-20230303
PIONEER-BD-ROM__BDC-UD02-1.00-9EE1C4B1-8490ID01-20121018
PIONEER-BD-RW__BDR-XU02JM-1.02-C0DAB4B1-8420ID02-20150428
PIONEER-BD-RW__BDR-UD02D-1.00-6AC7EE91-8410ID84-20130321
PIONEER-BD-RW__BDRUD02AS-1.01-4BF8CFFD-8410ID23-20131204
PIONEER-BD-RW__BDR-UD02-1.00-3F2D4DE0-8410ID01-20121018
PIONEER-BD-RW__BDR-UD02-1.00-544B8C03-8410ID19-20120823
PIONEER-BD-RW__BDR-XU02-1.13-A921893B-8420-20150428
PIONEER-BD-RW__BDR-XU03JM-1.04-8BDA3B5F-8520ID02-20230313
PIONEER-BD-RW__BDR-UD03D-1.00-6B6F48FD-8510ID84-20140514
PIONEER-BD-RW__BDR-XU03J-1.03-891BC34A-8520ID69-20150629
PIONEER-BD-RW__BDR-XU03J-1.05-17BC64F2-8520ID69-20230308

PIONEER-BD-RW__BDRUD03AS-1.00-27217C79-8510ID23-20140401
PIONEER-BD-RW__BDR-UD03-1.00-9E3A79AB-8510ID19-20130809
PIONEER-BD-RW__BDR-UD03-1.03-902EEB30-8510ID19-20150514
PIONEER-BD-RW__BDR-UD03-1.05-E49B95C0-8510-20151124
PIONEER-BD-RW__BDR-UD03-1.10-A059FCFD-8511-20170418
PIONEER-BD-RW__BDR-UD03-1.11-A522092F-8511-20181128
PIONEER-BD-RW__BDR-UD03-1.14-F39BF9BC-8511-20200615
PIONEER-BD-RW__BDR-XU03-1.03-A2589FEC-8520-20150629
PIONEER-BD-RW__BDR-S09JX-1.31-86811DD1-8600ID72-20150525
PIONEER-BD-RW__BDR-S09JX-1.32-6A5E6CDC-8600ID72-20150825
PIONEER-BD-RW__BDR-S09JX-1.33-F171979C-8600ID72-20151209
PIONEER-BD-RW__BDR-S09JX-1.34-4B10A330-8600ID72-20160425
PIONEER-BD-RW__BDR-S09JX-1.50-2DB8CDB7-8600ID72-20171221
PIONEER-BD-RW__BDR-S09JX-1.51-87336E5B-8600ID72-20180508
PIONEER-BD-RW__BDR-S09JX-1.52-984EC28B-8600ID72-20190111
PIONEER-BD-RW__BDR-S09JX-1.54-1C240838-8600ID72-20200721
PIONEER-BD-RW__BDR-S09JX-1.55-D6CDF9AC-8600ID72-20230216
PIONEER-BD-RW__BDR-209-1.20-81DE65E2-8600ID81-20140408
PIONEER-BD-RW__BDR-209-1.30-617FCF6E-8600ID81-20141205
PIONEER-BD-RW__BDR-209-1.31-EBFDDAB0-8600ID81-20150525
PIONEER-BD-RW__BDR-209-1.32-7A3EB286-8600ID81-20150825
PIONEER-BD-RW__BDR-209-1.33-A2F4E5CF-8600ID81-20151209
PIONEER-BD-RW__BDR-209-1.34-5FE47591-8600ID81-20160425
PIONEER-BD-RW__BDR-209-1.50-3269FF97-8600ID81-20171221
PIONEER-BD-RW__BDR-209-1.51-43826180-8601ID81-20180508
PIONEER-BD-RW__BDR-209-1.51-D8A59209-8600ID81-20180508
PIONEER-BD-RW__BDR-209D-1.10-44290838-8600ID61-20130910
PIONEER-BD-RW__BDR-209D-1.20-90EB76E2-8600ID61-20140408
PIONEER-BD-RW__BDR-209D-1.30-6901C899-8600ID61-20141205
PIONEER-BD-RW__BDR-209D-1.31-8CF13BF3-8600ID61-20150525
PIONEER-BD-RW__BDR-209D-1.32-F3AD8FFF-8600ID61-20150825
PIONEER-BD-RW__BDR-209D-1.33-CC733748-8600ID61-20151209
PIONEER-BD-RW__BDR-209D-1.34-FCF25369-8600ID61-20160425
PIONEER-BD-RW__BDR-209D-1.50-7F6800F0-8600ID61-20171221
PIONEER-BD-RW__BDR-209D-1.50-F67F9D64-8601ID61-20171221
PIONEER-BD-RW__BDR-209D-1.51-148709AB-8600ID61-20180508
PIONEER-BD-RW__BDR-209D-1.51-664813FF-8601ID61-20180508
PIONEER-BD-RW__BDR-209M-1.10-C441B62A-8600ID60-20130910
PIONEER-BD-RW__BDR-209M-1.20-52328626-8600-20140408
PIONEER-BD-RW__BDR-209M-1.20-5FF17367-8600ID58-20140408
PIONEER-BD-RW__BDR-209M-1.20-D1B39D1C-8600ID60-20140408
PIONEER-BD-RW__BDR-209M-1.30-3963D829-8600-20141205
PIONEER-BD-RW__BDR-209M-1.30-8AB26DA4-8600ID58-20141205
PIONEER-BD-RW__BDR-209M-1.30-CF3C8A07-8600ID60-20141205
PIONEER-BD-RW__BDR-209M-1.31-05D1FFCC-8600ID58-20150525
PIONEER-BD-RW__BDR-209M-1.31-6A320FF5-8600-20150525
PIONEER-BD-RW__BDR-209M-1.31-EF8C9405-8600ID60-20150525
PIONEER-BD-RW__BDR-209M-1.32-1DB7D5CF-8600-20150825
PIONEER-BD-RW__BDR-209M-1.32-83131CAD-8600ID58-20150825
PIONEER-BD-RW__BDR-209M-1.32-8DA82B4D-8600ID60-20150825
PIONEER-BD-RW__BDR-209M-1.33-066E4E6C-8600ID58-20151209

PIONEER-BD-RW__BDR-209M-1.33-6AFEC12B-8600ID60-20151209
PIONEER-BD-RW__BDR-209M-1.33-94F4337C-8600-20151209
PIONEER-BD-RW__BDR-209M-1.34-0272A73D-8600-20160425
PIONEER-BD-RW__BDR-209M-1.34-C20F2E95-8600ID60-20160425
PIONEER-BD-RW__BDR-209M-1.34-F687C68A-8600ID58-20160425
PIONEER-BD-RW__BDR-209M-1.50-211A9772-8600-20171221
PIONEER-BD-RW__BDR-209M-1.50-24E51C0C-8600ID58-20171221
PIONEER-BD-RW__BDR-209M-1.50-95A0C8DF-8601ID60-20171221
PIONEER-BD-RW__BDR-209M-1.50-9D6A6DAD-8600ID60-20171221
PIONEER-BD-RW__BDR-209M-1.51-388F93C7-8601ID60-20180508
PIONEER-BD-RW__BDR-209M-1.51-7961AC0B-8600ID60-20180508
PIONEER-BD-RW__BDR-209M-1.51-B3D6CC1C-8600ID58-20180508
PIONEER-BD-RW__BDR-209M-1.51-C74EAD09-8600-20180508
PIONEER-BD-RW__BDR-209M-1.52-8706173F-8600ID58-20190111
PIONEER-BD-RW__BDR-209M-1.52-EF61A725-8601ID60-20190111
PIONEER-BD-RW__BDR-209M-1.52-FFD20FFB-8600ID60-20190111
PIONEER-BD-RW__BDR-209M-1.54-1D807079-8601ID60-20200721
PIONEER-BD-RW__BDR-209M-1.54-8538B3B7-8600ID60-20200721
PIONEER-BD-RW__BDR-209M-1.54-D741421C-8600ID58-20200721
PIONEER-BD-RW__BDR-209M-1.55-164AE2C5-8600ID58-20230216
PIONEER-BD-RW__BDR-209M-1.55-4CF66C4B-8600ID60-20230216
PIONEER-BD-RW__BDR-209M-1.55-A866E45D-8601ID60-20230203
PIONEER-BD-RW__BDR-209M-8.11-4B155CED-8600ID52-20140116
PIONEER-BD-RW__BDR-209M-8.50-FDCF3D4E-8601ID52-20171221
PIONEER-BD-RW__BDR-S09-1.10-3F9C188D-8600ID43-20131015
PIONEER-BD-RW__BDR-S09-1.20-B23B14F9-8600ID43-20140408
PIONEER-BD-RW__BDR-S09-1.30-057E2FC3-8600ID43-20141205
PIONEER-BD-RW__BDR-S09-1.31-8D601423-8600ID43-20150525
PIONEER-BD-RW__BDR-S09-1.32-8F7EC102-8600ID43-20150825
PIONEER-BD-RW__BDR-S09-1.33-E5520C71-8600ID43-20151209
PIONEER-BD-RW__BDR-S09-1.34-57B19FCF-8600ID43-20160425
PIONEER-BD-RW__BDR-S09-1.50-E675168C-8600ID43-20171221
PIONEER-BD-RW__BDR-S09-1.51-2F7262DC-8601ID43-20180508
PIONEER-BD-RW__BDR-S09-1.51-3677F22A-8600ID43-20180508
PIONEER-BD-RW__BDR-S09-1.52-AF457A03-8601ID43-20190111
PIONEER-BD-RW__BDR-S09-1.52-B9B2735B-8600ID43-20190111
PIONEER-BD-RW__BDR-S09-1.54-16A43563-8601ID43-20200721
PIONEER-BD-RW__BDR-S09-1.54-7E7BBB7B-8600ID43-20200721
PIONEER-BD-RW__BDR-S09-1.55-9A434554-8601ID43-20230203
PIONEER-BD-RW__BDR-S09-1.55-B646650C-8600ID43-20230216
PIONEER-BD-RW__BDR-XS06JL-1.10-8AE8B9AB-8722ID03-20170622
PIONEER-BD-RW__BDR-XS06JL-1.11-A7B190A5-8722ID03-20230116
PIONEER-BD-RW__BDR-XS06JM-1.11-160979EF-8722ID02-20230116
PIONEER-BD-RW__BDR-XS06-1.00-A6B89DAF-8721-20150109
PIONEER-BD-RW__BDR-XS06-1.01-5BD07E84-8721ID69-20150324
PIONEER-BD-RW__BDR-XS06-1.01-89148930-8721-20150324
PIONEER-BD-RW__BDR-XS06-1.10-21C6167D-8722-20170622
PIONEER-BD-RW__BDR-XS06-1.10-50D93BD9-8722ID69-20170622
PIONEER-BD-RW__BDR-XS06-1.11-8A13909D-8722ID69-20230116
PIONEER-BD-RW__BDR-XS06-1.11-D1C9D539-8722-20230116
PIONEER-BD-RW__BDR-WX1DM-1.00-4F4BED7B-8801ID36-20221025

PIONEER-BD-RW__BDR-WX1DM-1.01-E549A85C-8801ID36-20231027
PIONEER-BD-RW__BDR-S11JX-1.02-625BF8BE-8800ID72-20170223
PIONEER-BD-RW__BDR-S11JX-1.50-D1B18416-8800ID72-20171221
PIONEER-BD-RW__BDR-S11JX-1.51-634BC71A-8800ID72-20180508
PIONEER-BD-RW__BDR-S11JX-1.51-F362267E-8801ID72-20180508
PIONEER-BD-RW__BDR-S11JX-1.52-124CD3F1-8800ID72-20190111
PIONEER-BD-RW__BDR-S11JX-1.52-8706F7EA-8801ID72-20190111
PIONEER-BD-RW__BDR-S11JX-1.53-0CAB0042-8801ID72-20200803
PIONEER-BD-RW__BDR-S11JX-1.53-DF931D24-8800ID72-20200803
PIONEER-BD-RW__BDR-S11JX-1.54-1A867E4C-8801ID72-20230123
PIONEER-BD-RW__BDR-S11JX-1.54-1D7AD494-8800ID72-20230208
PIONEER-BD-RW__BDR-211M-1.02-6DD2E19C-8800-20170223
PIONEER-BD-RW__BDR-211M-1.02-87BA6DC7-8800ID60-20170223
PIONEER-BD-RW__BDR-211M-1.50-2FA0A28C-8801ID60-20171221
PIONEER-BD-RW__BDR-211M-1.50-5BE18B0F-8800ID58-20171221
PIONEER-BD-RW__BDR-211M-1.50-A291E78D-8800-20171221
PIONEER-BD-RW__BDR-211M-1.50-FC4245B7-8800ID60-20171221
PIONEER-BD-RW__BDR-211M-1.51-0BBF4615-8800ID60-20180508
PIONEER-BD-RW__BDR-211M-1.51-2689307C-8801-20180508
PIONEER-BD-RW__BDR-211M-1.51-4C1159D3-8800-20180508
PIONEER-BD-RW__BDR-211M-1.51-8A93799D-8801ID58-20180508
PIONEER-BD-RW__BDR-211M-1.51-B020FFBA-8800ID58-20180508
PIONEER-BD-RW__BDR-211M-1.51-B7756C3E-8801ID60-20180508
PIONEER-BD-RW__BDR-211M-1.52-959A61E2-8801ID60-20190111
PIONEER-BD-RW__BDR-211M-1.52-BCE8CAB4-8801ID58-20190111
PIONEER-BD-RW__BDR-211M-1.52-D8162CDD-8800ID58-20190111
PIONEER-BD-RW__BDR-211M-1.52-DA133C56-8800ID60-20190111
PIONEER-BD-RW__BDR-211M-1.53-326AC898-8801ID60-20200803
PIONEER-BD-RW__BDR-211M-1.53-6FBA3899-8800ID60-20200803
PIONEER-BD-RW__BDR-211M-1.53-BC596F5C-8801ID58-20200803
PIONEER-BD-RW__BDR-211M-1.53-F134C6C2-8800ID58-20200803
PIONEER-BD-RW__BDR-211M-1.54-030696ED-8801ID58-20230123
PIONEER-BD-RW__BDR-211M-1.54-CBB356F0-8800ID60-20230208
PIONEER-BD-RW__BDR-211M-1.54-E63084AF-8800ID58-20230208
PIONEER-BD-RW__BDR-211M-1.54-EA3911AF-8801ID60-20230123
PIONEER-BD-RW__BDR-S11-1.02-98F6C76F-8800ID43-20170223
PIONEER-BD-RW__BDR-S11-1.50-2CD5C009-8800ID43-20171221
PIONEER-BD-RW__BDR-S11-1.51-D0795CDA-8801ID43-20180508
PIONEER-BD-RW__BDR-S11-1.51-FD42A614-8800ID43-20180508
PIONEER-BD-RW__BDR-S11-1.52-0400B8D9-8801ID43-20190111
PIONEER-BD-RW__BDR-S11-1.52-7987B01B-8800ID43-20190111
PIONEER-BD-RW__BDR-S11-1.53-341479DB-8800ID43-20200803
PIONEER-BD-RW__BDR-S11-1.53-D92F3D6B-8801ID43-20200803
PIONEER-BD-RW__BDR-S11-1.54-200D66C9-8800ID43-20230208
PIONEER-BD-RW__BDR-S11-1.54-328C9BB4-8801ID43-20230123
PIONEER-BD-RW__BDR-UD04D-1.20-C43F4D9B-8A10ID84-20170926
PIONEER-BD-RW__BDR-UD04-1.00-4B3560E3-8A10-20170210
PIONEER-BD-RW__BDR-UD04-1.10-431D03CF-8A10-20170425
PIONEER-BD-RW__BDR-UD04-1.11-72FD7DDB-8A10-20181128
PIONEER-BD-RW__BDR-UD04-1.14-489CDFD6-8A10-20200615
PIONEER-BD-RW__BDR-UD04-1.21-96EC3DA5-8A10ID19-20180426

PIONEER-BD-RW__BDR-XD06U-1.11-A16AD1CA-8B30ID69-20170622
PIONEER-BD-RW__BDR-XD06U-1.12-490F0B32-8B30ID69-20230303
PIONEER-BD-RW__BDR-XD07U-1.00-53B79EBC-8D31ID69-20171030
PIONEER-BD-RW__BDR-XD07U-1.01-AA7B8585-8D31ID69-20181203
PIONEER-BD-RW__BDR-XD07U-1.01-FE438337-8D31ID05-20181203
PIONEER-BD-RW__BDR-XD07U-1.03-27184B96-8D31ID05-20200820
PIONEER-BD-RW__BDR-XD07U-1.03-BE6D47C9-8D31ID69-20200820
PIONEER-BD-RW__BDR-XD07U-1.04-8E435F7E-8D31ID05-20220531
PIONEER-BD-RW__BDR-XD07U-1.04-EBB2E1B0-8D31ID69-20220531
PIONEER-BD-RW__BDR-XD07U-1.05-66A985F3-8D31ID69-20230106
PIONEER-BD-RW__BDR-XD07U-1.05-AA31CA41-8D31ID05-20230106
PIONEER-BD-RW__BDR-XD07U-1.06-E2F8E5F9-8D31ID69-20241009
PIONEER-BD-RW__BDR-AD07-1.01-28582C83-8D30ID32-20181203
PIONEER-BD-RW__BDR-AD07-1.03-FFA23F11-8D30ID32-20200820
PIONEER-BD-RW__BDR-AD07-1.04-0A009E17-8D30ID32-20220531
PIONEER-BD-RW__BDR-AD07-1.06-A5C56D65-8D30ID32-20241009
PIONEER-BD-RW__BDR-XD07-1.00-9ED80351-8D30ID36-20171030
PIONEER-BD-RW__BDR-XD07-1.01-9B267B9C-8D30ID36-20181203
PIONEER-BD-RW__BDR-XD07-1.02-09F745D9-8D30-20190905
PIONEER-BD-RW__BDR-XD07-1.03-4F94511A-8D30ID36-20200820
PIONEER-BD-RW__BDR-XD07-1.03-784E4A86-8D30-20200820
PIONEER-BD-RW__BDR-XD07-1.03-97A65EF6-8D30ID35-20200820
PIONEER-BD-RW__BDR-XD07-1.04-8D6598C6-8D30ID35-20220531
PIONEER-BD-RW__BDR-XD07-1.04-9F4B2B79-8D30ID36-20220531
PIONEER-BD-RW__BDR-XD07-1.04-CE57F5EB-8D30-20220531
PIONEER-BD-RW__BDR-XD07-1.05-7F95F332-8D30ID36-20230106
PIONEER-BD-RW__BDR-XD07-1.05-BCE44855-8D30ID35-20230106
PIONEER-BD-RW__BDR-XD07-1.06-3573EC33-8D30ID36-20241009
PIONEER-BD-RW__BDR-XS07JL-1.00-33DEBC96-8E20ID03-20190107
PIONEER-BD-RW__BDR-XS07JL-1.01-0DC83800-8E20ID03-20200903
PIONEER-BD-RW__BDR-XS07JL-1.02-F2779DCE-8E20ID03-20221024
PIONEER-BD-RW__BDR-XS07JL-1.03-4F963398-8E20ID03-20230106
PIONEER-BD-RW__BDR-XS07JL-1.04-782E07B7-8E20ID03-20241009
PIONEER-BD-RW__BDR-XS07JM-1.04-AC5DD8C6-8E20ID02-20241009
PIONEER-BD-RW__BDR-XS07-1.00-DCD316A9-8E20-20190107
PIONEER-BD-RW__BDR-XS07-1.01-A470FBFD-8E20-20200903
PIONEER-BD-RW__BDR-XS07-1.02-E95A355C-8E20-20221024
PIONEER-BD-RW__BDR-XS07-1.03-774273E8-8E20-20230106
PIONEER-BD-RW__BDR-XS07-1.04-B81FE833-8E20-20241009
PIONEER-BD-RW__BDR-XS07U-1.00-D1E5568A-8E21ID05-20190107
PIONEER-BD-RW__BDR-XS07U-1.01-1534D764-8E21ID05-20200903
PIONEER-BD-RW__BDR-XS07U-1.01-32129473-8E21ID69-20200903
PIONEER-BD-RW__BDR-XS07U-1.02-4AFD809E-8E21ID69-20221024
PIONEER-BD-RW__BDR-XS07U-1.02-CA5C627C-8E21ID05-20221024
PIONEER-BD-RW__BDR-XS07U-1.03-AC58B907-8E21ID69-20230106
PIONEER-BD-RW__BDR-XS07U-1.03-CF9A3571-8E21ID05-20230106
PIONEER-BD-RW__BDR-XS07U-1.04-766B0BCE-8E21ID05-20241009
PIONEER-BD-RW__BDR-212BK-1.00-437E5060-8F00ID81-20190110
PIONEER-BD-RW__BDR-S12JX-1.00-66AF20D1-8F01ID72-20190110
PIONEER-BD-RW__BDR-S12JX-1.01-2AE09FD4-8F01ID72-20200721
PIONEER-BD-RW__BDR-S12JX-1.03-F2B2A100-8F01ID72-20221013

PIONEER-BD-RW__BDR-S12JX-1.05-E123F158-8F01ID72-20230801
PIONEER-BD-RW__BDR-209M-8.53-31235FEA-8F00ID52-20190307
PIONEER-BD-RW__BDR-212D-1.00-52E9FE5C-8F00ID61-20190110
PIONEER-BD-RW__BDR-212D-1.01-F567BFF5-8F00ID61-20200721
PIONEER-BD-RW__BDR-212D-1.02-22C9CC74-8F00ID61-20220316
PIONEER-BD-RW__BDR-212D-1.03-91B6BA99-8F00ID61-20221013
PIONEER-BD-RW__BDR-212M-1.00-D02AACCF-8F00ID56-20190110
PIONEER-BD-RW__BDR-212M-1.01-5013125C-8F00ID56-20200721
PIONEER-BD-RW__BDR-212M-1.02-DDCB943E-8F00ID56-20220309
PIONEER-BD-RW__BDR-212M-1.03-F672A364-8F00ID56-20221013
PIONEER-BD-RW__BDR-212M-1.04-7DD284B0-8F00ID56-20221220
PIONEER-BD-RW__BDR-212M-1.05-E65C1C2D-8F00ID56-20230801
PIONEER-BD-RW__BDR-212U-1.00-49FD4495-8F01ID58-20190110
PIONEER-BD-RW__BDR-212U-1.01-CD721A59-8F01ID58-20200721
PIONEER-BD-RW__BDR-212U-1.01-DFAA920B-8F01ID83-20200721
PIONEER-BD-RW__BDR-212U-1.02-6023BC47-8F01ID83-20220307
PIONEER-BD-RW__BDR-212U-1.02-E5C95BE2-8F01ID58-20220307
PIONEER-BD-RW__BDR-212U-1.03-BE400CC8-8F01ID58-20221013
PIONEER-BD-RW__BDR-212U-1.04-80F9AA69-8F01ID58-20221220
PIONEER-BD-RW__BDR-212U-1.05-D4BF8E39-8F01ID58-20230801
PIONEER-BD-RW__BDR-212V-1.00-351EBAC1-8F00ID06-20200807
PIONEER-BD-RW__BDR-212V-1.01-140EA303-8F00ID06-20210720
PIONEER-BD-RW__BDR-S12-1.00-B05CF9EE-8F00ID45-20190110
PIONEER-BD-RW__BDR-S12-1.01-F83E6EB3-8F00ID45-20200721
PIONEER-BD-RW__BDR-S12-1.03-9FF3C094-8F00ID45-20221013
PIONEER-BD-RW__BDR-S12-1.04-17CA79F2-8F00ID45-20221220
PIONEER-BD-RW__BDR-S12U-1.00-9F4CFBF7-8F01ID43-20190110
PIONEER-BD-RW__BDR-S12U-1.01-1C080B0C-8F01ID43-20200721
PIONEER-BD-RW__BDR-S12U-1.02-F1ED7302-8F01ID43-20220307
PIONEER-BD-RW__BDR-S12U-1.03-13C675B1-8F01ID43-20221013
PIONEER-BD-RW__BDR-S12U-1.04-67BA493A-8F01ID43-20221220
PIONEER-BD-RW__BDR-S12U-1.05-91ED53B2-8F01ID43-20230801
PIONEER-BD-RW__BDR-X12-1.02-003EFC2C-9000ID15-20200122
PIONEER-BD-RW__BDR-X12-1.02-B87821FD-9000ID56-20200122
PIONEER-BD-RW__BDR-X12-1.03-F01BF4EF-9000ID56-20200805
PIONEER-BD-RW__BDR-X12-1.03-F6C83C2C-9000ID15-20200805
PIONEER-BD-RW__BDR-X12-1.04-2E189FF3-9000ID56-20220218
PIONEER-BD-RW__BDR-X12-1.04-4CA07005-9000ID15-20220218
PIONEER-BD-RW__BDR-X12-1.05-137BD167-9000ID56-20221011
PIONEER-BD-RW__BDR-X12-1.06-0F719336-9000ID15-20221220
PIONEER-BD-RW__BDR-X12-1.06-E655F32A-9000ID56-20221220
PIONEER-BD-RW__BDR-X12-1.07-A857DC00-9000ID15-20230801
PIONEER-BD-RW__BDR-X12U-1.02-6149B820-9001ID43-20200122
PIONEER-BD-RW__BDR-X12U-1.03-31D36981-9001ID43-20200805
PIONEER-BD-RW__BDR-X12U-1.04-C92DDCA7-9001ID43-20220210
PIONEER-BD-RW__BDR-X12U-1.06-176813DE-9001ID43-20221220
PIONEER-BD-RW__BDR-X12U-1.07-E01E5D32-9001ID43-20230801
PIONEER-BD-RW__BDR-S13JX-1.01-F374183B-9201ID72-20210819
PIONEER-BD-RW__BDR-S13JX-1.02-6A2F955E-9201ID72-20220210
PIONEER-BD-RW__BDR-S13JX-1.03-E9BA8ECC-9201ID72-20220726
PIONEER-BD-RW__BDR-S13JX-1.04-B3338427-9201ID72-20221212

PIONEER-BD-RW__BDR-S13JX-1.05-DCFDE474-9201ID72-20230801
PIONEER-BD-RW__BDR-213M-1.03-E1AC619F-9200ID56-20220726
PIONEER-BD-RW__BDR-213M-1.04-E654B55A-9200ID56-20221212
PIONEER-BD-RW__BDR-213M-1.05-46DB8D4C-9200ID56-20230801
PIONEER-BD-RW__BDR-213U-1.01-74DF37BF-9201ID58-20210819
PIONEER-BD-RW__BDR-213U-1.02-670B1681-9201ID58-20220217
PIONEER-BD-RW__BDR-213U-1.04-B9D3A7CD-9201ID58-20221212
PIONEER-BD-RW__BDR-213U-1.05-947C64B6-9201ID58-20230801
PIONEER-BD-RW__BDR-S13U-1.01-CE21042E-9201ID43-20210819
PIONEER-BD-RW__BDR-S13U-1.02-04230933-9201ID43-20220216
PIONEER-BD-RW__BDR-S13U-1.03-DFE22909-9201ID43-20220726
PIONEER-BD-RW__BDR-S13U-1.04-A00D78F7-9201ID43-20221212
PIONEER-BD-RW__BDR-S13U-1.05-86F002D5-9201ID43-20230801
PIONEER-BD-RW__BDR-XD08U-1.00-14B331D4-9331ID69-20210512
PIONEER-BD-RW__BDR-XD08U-1.00-487B87C5-9331ID05-20220403
PIONEER-BD-RW__BDR-XD08U-1.01-1AC12F40-9331ID69-20221011
PIONEER-BD-RW__BDR-XD08U-1.01-6293EE04-9331ID05-20221011
PIONEER-BD-RW__BDR-XD08U-1.02-7CF2F842-9331ID69-20221227
PIONEER-BD-RW__BDR-XD08U-1.02-9CF85784-9331ID05-20221227
PIONEER-BD-RW__BDR-XD08U-1.04-393664D7-9331ID05-20241009
PIONEER-BD-RW__BDR-XD08U-1.04-96D53322-9331ID69-20241009
PIONEER-BD-RW__BDR-AD08-1.00-49712FFD-9330ID32-20210322
PIONEER-BD-RW__BDR-AD08-1.01-B38B9466-9330ID32-20221011
PIONEER-BD-RW__BDR-AD08-1.04-D33FAD48-9330ID32-20241009
PIONEER-BD-RW__BDR-XD08-1.00-93E02B4C-9330ID36-20210322
PIONEER-BD-RW__BDR-XD08-1.01-547FAF30-9330ID35-20221011
PIONEER-BD-RW__BDR-XD08-1.01-B7CB6212-9330ID36-20221011
PIONEER-BD-RW__BDR-XD08-1.01-DDCDBEC6-9330-20221011
PIONEER-BD-RW__BDR-XD08-1.02-1D5A9FFA-9330ID35-20221227
PIONEER-BD-RW__BDR-XD08-1.02-96F5D4DC-9330-20221227
PIONEER-BD-RW__BDR-XD08-1.02-F9A908B9-9330ID36-20221227
PIONEER-BD-RW__BDR-XD08-1.04-ADCE17D3-9330ID36-20241009
PIONEER-BD-RW__BDR-XD08-1.04-AFB1246B-9330ID35-20241009
PIONEER-BD-RW__BDR-X13-1.01-1872DAE4-9400ID15-20220218
PIONEER-BD-RW__BDR-X13-1.03-41DA76BE-9400ID15-20221212
PIONEER-BD-RW__BDR-X13-1.03-BB49ED7A-9400ID56-20221212
PIONEER-BD-RW__BDR-X13-1.04-DE82C220-9400ID56-20230801
PIONEER-BD-RW__BDR-X13-1.04-DEA61B13-9400ID15-20230801
PIONEER-BD-RW__BDR-X13U-1.01-03AF521E-9401ID43-20220210
PIONEER-BD-RW__BDR-X13U-1.01-1061E8AA-9401ID29-20220228
PIONEER-BD-RW__BDR-X13U-1.02-572A2EA7-9401ID29-20220726
PIONEER-BD-RW__BDR-X13U-1.02-E6B2C0F6-9401ID43-20220726
PIONEER-BD-RW__BDR-X13U-1.03-AE4007A4-9401ID43-20221212
PIONEER-BD-RW__BDR-X13U-1.03-D9E26B6B-9401ID29-20221212
PIONEER-BD-RW__BDR-X13U-1.04-0C172FDF-9401ID43-20230801
PIONEER-BD-RW__BDR-X13U-1.04-5BAD7675-9401ID29-20230801
PIONEER-BD-RW__BDR-X13X-1.04-CB1C42F8-9401ID10-20230801
PIONEER-BD-RW__BDR-XS08U-1.00-87FED491-9621ID69-20221011
PIONEER-BD-RW__BDR-XS08U-1.01-5388C36A-9621ID69-20221227
PIONEER-BD-RW__BDR-XS08U-1.03-3F701552-9621ID69-20241009
ASUS-BW-12D1S-U-E301-82D4D675-8301ID71-20130225

```

ASUS-BW-12D1S-U-E401-25424135-8600ID44-20130910
ASUS-BW-12D1S-U-E402-81C0FD1C-8600ID44-20180115
ASUS-BW-12D1S-U-E411-E3916CB0-8601ID44-20171221
ASUS-BW-16D1H-U-E104-095E2160-8600ID71-20170614
ASUS-BW-16D1H-U-E114-968CF7BA-8601ID71-20171221
ASUS-BW-16D1H-U-E115-D93DA305-8F00ID71-20190307
ASUS-BW-16D1H-U-E116-D0CE65A7-8F00ID71-20200721
ASUS-BW-16D1X-U-E101-2AD78862-8600ID76-20151020
ASUS-BW-16D1X-U-E102-523563E4-8600ID76-20180115
ASUS-BW-16D1X-U-E102-628CCEAB-8600ID76-20170115
ASUS-BW-16D1X-U-E111-95C4500C-8601ID76-20171221
ASUS-BW-16D1X-U-E113-05C95848-8F00ID76-20200721
ASUS-SBC-06D2X-U-1.03-4708C895-8590ID22-20161216
ASUS-SBC-06D2X-U-1.10-A05DF1FA-8591ID22-20170418
ASUS-SBW-06D2X-U-1.03-19A80D16-8510ID22-20161216
ASUS-SBW-06D2X-U-1.10-9C3BA3C8-8510ID22-20170418
ASUS-SBW-06D5H-U-E101-3F03CED5-8511ID26-20180822
ASUS-SBW-06D5H-U-E102-85EB82CA-8511ID26-20230420
PIONEER-BDW-PR1EPDVP100-1.00-C17EC4E7-8680ID79-20151127

```

supported - original vendor firmware (old type, MTK19XX): 65 firmware(s):

```

ASUS-BC-12B1ST_b-1.00-_130614-x-211306141158
ASUS-BC-12B1ST_b-3.00-W004704-211512151340
ASUS-BC-12D2HT-1.00-_130614-x-211306141200
ASUS-BC-12D2HT-3.00-W004704-211512091147
ASUS-BW-12B1ST_a-1.00-E101701-211304231147
ASUS-BW-14D1XT-1.00-M103703-210000000000
ASUS-BW-16D1H-U-A101-W000600-211412080959
ASUS-BW-16D1HT-1.01-W100600-211302051930
HL-DT-ST-BD-RE_BE14NU40-1.00-N0G43G4-211206262029
HL-DT-ST-BD-RE_BE14NU40-1.01-N001601-211406161935
HL-DT-ST-BD-RE_BE14NU40-1.01-N003803-211406251441
HL-DT-ST-BD-RE_BE14NU40-1.01-N005905-211408221631
HL-DT-ST-BD-RE_BH14NS40-1.00-N1A11A1-211201171401
HL-DT-ST-BD-RE_BH14NS40-1.00-N1A37A3-211205021346
HL-DT-ST-BD-RE_BH14NS40-1.00-N1A44A4-211206161823
HL-DT-ST-BD-RE_BH14NS40-1.01-N1A12A1-211304042319
HL-DT-ST-BD-RE_BH14NS40-1.02-N0A02A0-211312061453
HL-DT-ST-BD-RE_BH14NS40-1.03-N0A09A0-211405071012
HL-DT-ST-BD-RE_BH14NS48-1.00-N1A44A4-211206161825
HL-DT-ST-BD-RE_BH14NS48-1.01-N1A03A0-210000000000
HL-DT-ST-BD-RE_BH14NS48-1.02-N1A12A1-211304042322
HL-DT-ST-BD-RE_BH14NS48-1.03-N0A02A0-211312061510
HL-DT-ST-BD-RE_BH16NS40-1.00-N1A29A2-211210311917
HL-DT-ST-BD-RE_BH16NS40-1.01-N1A12A1-211304042250
HL-DT-ST-BD-RE_BH16NS40-1.02-N0A02A0-211312061535
HL-DT-ST-BD-RE_BH16NS40-1.03-N0A03A0-211403261115
HL-DT-ST-BD-RE_BH16NS40-1.03-N0C06C0-211505261714
HL-DT-ST-BD-RE_BH16NS48-1.00-N1A29A2-211210311913

```

HL-DT-ST-BD-RE_BH16NS48-1.01-N1A12A1-211304042252
HL-DT-ST-BD-RE_BH16NS48-1.02-N0A02A0-211312061545
HL-DT-ST-BD-RE_BH40N-A102-D0A22A2-211303262335
HL-DT-ST-BD-RE_BH40N-AS00-U101901-211304242023
HL-DT-ST-BD-RE_WH14NS40-1.00-N1A26A2-211202091126
HL-DT-ST-BD-RE_WH14NS40-1.00-N1A37A3-211204261630
HL-DT-ST-BD-RE_WH14NS40-1.00-N1A44A4-211206161828
HL-DT-ST-BD-RE_WH14NS40-1.01-N1A12A1-211304042325
HL-DT-ST-BD-RE_WH14NS40-1.02-N0A02A0-211312061523
HL-DT-ST-BD-RE_WH14NS40-1.03-N0A09A0-211403261105
HL-DT-ST-BD-RE_WH14NS40-1.03-N0C08C0-211505261653
HL-DT-ST-BD-RE_WH14NS40-1514-N100400-211205301654
HL-DT-ST-BD-RE_WH16NS40-1.00-N1A12A1-211304041441
HL-DT-ST-BD-RE_WH16NS40-1.01-N0A02A0-211312061658
HL-DT-ST-BD-RE_WH16NS40-1.02-N0A00A0-211405071026
HL-DT-ST-BD-RE_WH16NS40-1.02-N0C00C0-211505261638
HL-DT-ST-BD-RE_WH16NS48-1.D3-N000700-211602041103
HL-DT-ST-BD-RE_WH16NS48-TSTQ-N000500-211508121144
HL-DT-ST-BDDVDRW_CH12NS30-1.00-N0A13A1-211303221728
HL-DT-ST-BDDVDRW_CH12NS30-1.00-N0A20A2-211306131532
HL-DT-ST-BDDVDRW_CH12NS30-1.01-N0A02A0-211312061614
HL-DT-ST-BDDVDRW_CH12NS30-1.02-N0A05A0-211404241908
HL-DT-ST-BDDVDRW_CH12NS40-1.00-N002202-211602231047
HL-DT-ST-BDDVDRW_CH30N-AS00-S002102-211306141459
HL-DT-ST-BDDVDRW_CP50NS20-1.00-N004904-211409041512
HL-DT-ST-BDDVDRW_CP50NS20-1.00-N007307-211412161028
HL-DT-ST-BDDVDRW_CU20N-1.00-N003203-211412161022
HL-DT-ST-BDDVDRW_UH12NS30-1.00-N0A13A1-211303221725
HL-DT-ST-BDDVDRW_UH12NS30-1.00-N0A20A2-211306131457
HL-DT-ST-BDDVDRW_UH12NS30-1.01-N0A02A0-211312061625
HL-DT-ST-BDDVDRW_UH12NS30-1.02-N0A04A0-211403261141
HL-DT-ST-BDDVDRW_UH12NS30-1.03-N0A05A0-211404241900
HL-DT-ST-BDDVDRW_UH12NS40-1.00-N000200-211602231042
HL-DT-ST-DVDRWBD_CH30N-A101-D000300-210000000000
hp-BD-RE_BH40N-B7C6-P0A12A1-211303262313
hp-BDDVDRW_CH30L-BC56-P0B00B0-210000000000
hp-BDDVDRW_CU10N-B1C0-P015115-211307031530

unsupported - old firmware type 1:29 firmware(s):

hp-DVDWBD_TS-LB23P-0100-0309-
TSSTcorp-BDDVDW_SE-506BB-TS00-02.20-
TSSTcorp-BDDVDW_SE-506BB-TS00-11.13-
TSSTcorp-BDDVDW_SE-506BB-TS01-05.21-
TSSTcorp-BDDVDW_SE-506CB-TS00-04.24-
TSSTcorp-BDDVDW_SE-506CB-TS00-12.12-
TSSTcorp-BDDVDW_SE-506CB-TS01-05.12-
TSSTcorp-BDDVDW_SE-506CB-TS01-05.28-
TSSTcorp-BDDVDW_SE-506CB-TS02-01.07-
TSSTcorp-BDDVDW_SN-506BB-AF04-04.22-

TSSTcorp-BDDVDW_SN-506BB-GT01-01.31-
 TSSTcorp-BDDVDW_SN-506BB-GT03-07.31-
 TSSTcorp-BDDVDW_SN-506BB-GT06-01.05-
 TSSTcorp-BDDVDW_SN-506BB-GT08-06.17-
 TSSTcorp-BDDVDW_SN-506BB-JF01-11.27-
 TSSTcorp-BDDVDW_SN-506BB-SB00-07.10-
 TSSTcorp-BDDVDW_SN-506BB-SB00-11.13-
 TSSTcorp-BDDVDW_SN-506BB-TM01-09.23-
 TSSTcorp-BDDVDW_SN-506BB-TM01-12.11-
 TSSTcorp-DVDWBD_SE-406AB-TS00-04.20-
 TSSTcorp-DVDWBD_SH-B123A-MD03-03.31-
 TSSTcorp-DVDWBD_SH-B123A-SB03-12.03-
 TSSTcorp-DVDWBD_SH-B123A-SB04-03.31-
 TSSTcorp-DVDWBD_SH-B123L-SB00-05.11-
 TSSTcorp-DVDWBD_SH-B123L-SB02-08.16-
 TSSTcorp-DVDWBD_SH-B123L-SB03-12.03-
 TSSTcorp-DVDWBD_SH-B123L-SB04-03.31-
 TSSTcorp-DVDWBD_TS-LB23D-LB12-_0321-
 TSSTcorp-DVDWBD_TS-LB23D-SC02-06.07-

unsupported - old firmware type 2: 10 firmware(s):

hp-DVDWBD_SN-406AB-HH01-0116-
 TSSTcorp-BDDVDW_SE-506AB-TS00-09.06-
 TSSTcorp-BDDVDW_SE-506AB-TS01-01.31-
 TSSTcorp-BDDVDW_SN-506AB-SB00-01.31-
 TSSTcorp-DVDWBD_SN-406AB-AS01-09.25-
 TSSTcorp-DVDWBD_SN-406AB-AS02-03.05-
 TSSTcorp-DVDWBD_SN-406AB-SB00-10.05-
 TSSTcorp-DVDWBD_SN-406AB-SC00-06.18-
 TSSTcorp-DVDWBD_SN-406AB-TM00-07.11-
 TSSTcorp-DVDWBD_SN-406AB-TM01-05.15-

upgrade required - MK firmware available: 79 firmware(s):

ASUS-BC-12B1ST_b-3.01-W000900-211711291725
 ASUS-BC-12B1ST_b-3.11-W000300-211902271321
 ASUS-BC-12D2HT-3.01-W000900-211711151926
 ASUS-BC-12D2HT-3.11-W000300-211902271319
 ASUS-BW-16D1H-U-A203-W001501-211801111117
 ASUS-BW-16D1H-U-A204-W001001-211901041044
 ASUS-BW-16D1HT-3.03-W000000-211801191558
 ASUS-BW-16D1HT-3.10-W001601-211901041014
 ASUS-BW-16D1X-U-A104-W001001-211901041047
 HL-DT-ST-BD-RE_BE16NU50-1.02-N000500-211711201953
 HL-DT-ST-BD-RE_BE16NU50-1.04-N000300-212005081025
 HL-DT-ST-BD-RE_BH14NS50-1.01-N000000-211711281847
 HL-DT-ST-BD-RE_BH14NS50-1.03-N000400-212004211008

HL-DT-ST-BD-RE_BH14NS58-1.01-N000500-211711161557
HL-DT-ST-BD-RE_BH16NS40-NS50-1.03-N000000-211711201943
HL-DT-ST-BD-RE_BH16NS40-NS50-1.04-N001701-211901041338
HL-DT-ST-BD-RE_BH16NS40-NS50-1.05-N000600-212005061331
HL-DT-ST-BD-RE_BH16NS50-1.01-N000000-211712071200
HL-DT-ST-BD-RE_BH16NS50-1.03-N000400-212004210958
HL-DT-ST-BD-RE_BH16NS55-1.03-N000000-211711201704
HL-DT-ST-BD-RE_BH16NS55-1.04-N001701-211901041342
HL-DT-ST-BD-RE_BH16NS55-1.05-N000400-212004211049
HL-DT-ST-BD-RE_BH16NS58-1.01-N000500-211711161545
HL-DT-ST-BD-RE_BH16NS58-1.02-N001101-211901041359
HL-DT-ST-BD-RE_BH16NS60-1.00-N000500-211804030945
HL-DT-ST-BD-RE_BH16NS60-1.02-N000600-212005081014
HL-DT-ST-BD-RE_BP50NB40-NB50-1.01-N000200-211711231615
HL-DT-ST-BD-RE_BP50NB40-NB50-1.02-N000700-211811011016
HL-DT-ST-BD-RE_BP50NB40-NB50-1.03-N000800-212005070917
HL-DT-ST-BD-RE_BP50NB40-NB52-1.03-N000300-212107081603
HL-DT-ST-BD-RE_BP55EB40-NB50-1.01-N000200-211711231626
HL-DT-ST-BD-RE_BP55EB40-NB50-1.02-N000700-211811011033
HL-DT-ST-BD-RE_BP55EB40-NB50-1.02-N001801-211905031515
HL-DT-ST-BD-RE_BP55EB40-NB50-1.03-N000800-212005070924
HL-DT-ST-BD-RE_BP60NB10-1.00-N000200-211711211720
HL-DT-ST-BD-RE_BP60NB10-1.01-N001801-211905031534
HL-DT-ST-BD-RE_BP60NB10-1.02-N000800-212005070935
HL-DT-ST-BD-RE_BP60NB10-NB12-1.02-N000300-212107081556
HL-DT-ST-BD-RE_BP71N-1.00-S002602-212008050903
HL-DT-ST-BD-RE_BP71N-1.01-S000800-212009071143
HL-DT-ST-BD-RE_BU40N-1.01-R000000-211712221221
HL-DT-ST-BD-RE_BU40N-1.01-R001801-211910161032
HL-DT-ST-BD-RE_BU40N-1.02-N000100-211711202017
HL-DT-ST-BD-RE_BU40N-1.02-N001201-211711301218
HL-DT-ST-BD-RE_BU40N-1.02-R000200-212012011716
HL-DT-ST-BD-RE_BU40N-1.03-N000000-211810241934
HL-DT-ST-BD-RE_BU40N-1.04-N000500-212005061142
HL-DT-ST-BD-RE_BU40N-BN11-0000300-211711201351
HL-DT-ST-BD-RE_BU40N-BN12-0001001-211905141415
HL-DT-ST-BD-RE_BU40N-BU12-0001001-211902230922
HL-DT-ST-BD-RE_BU40N-FR07-J002202-211801221536
HL-DT-ST-BD-RE_BU40N-U100-3001801-211910161036
HL-DT-ST-BD-RE_BU40N-U101-M001201-211711301153
HL-DT-ST-BD-RE_BU50N-1.00-N000100-211711211006
HL-DT-ST-BD-RE_WH14NS40-NS50-1.03-N000600-211711211658
HL-DT-ST-BD-RE_WH14NS40-NS50-1.04-N001201-211901041351
HL-DT-ST-BD-RE_WH14NS40-NS50-1.05-N000900-212005061444
HL-DT-ST-BD-RE_WH16NS40-NS50-1.03-N000600-211711211653
HL-DT-ST-BD-RE_WH16NS40-NS50-1.05-N000900-212005061440
HL-DT-ST-BD-RE_WH16NS58-1.V1-N002102-211711201947
HL-DT-ST-BD-RE_WH16NS58-1.V2-N000100-211711231023
HL-DT-ST-BD-RE_WH16NS58-1.V5-N000900-211802070957
HL-DT-ST-BD-RE_WH16NS60-1.01-N000100-211711202000
HL-DT-ST-BD-RE_WH16NS60-1.02-N000100-211810291936

HL-DT-ST-BD-RE_WH16NS60-1.03-N000600-212005081010
HL-DT-ST-BD-RE_WP50NB40-NB50-1.01-N000200-211711231646
HL-DT-ST-BD-RE_WP50NB40-NB50-1.03-N000800-212005070929
HL-DT-ST-BDDVDRW_CH12NS40-1.01-N000400-211711211606
HL-DT-ST-BDDVDRW_CH12NS40-1.03-N000800-212005080957
HL-DT-ST-BDDVDRW_UH12NS40-1.01-N000200-211711231550
HL-DT-ST-BDDVDRW_UH12NS40-1.03-N000800-212005080959
HL-DT-ST-BD-RE_BE16NU50-INTM-N000800-212004231013
HL-DT-ST-BD-RE_BH16NS40-NS50-INTM-N000600-212002041513
HL-DT-ST-BD-RE_BH16NS60-INTM-N000400-212002181142
HL-DT-ST-BD-RE_BP50NB40-NB50-INTM-N000900-212003031607
HL-DT-ST-BD-RE_BP60NB10-INTM-N000900-212003031601
HL-DT-ST-BD-RE_BU40N-INTM-N000800-211907051444
HL-DT-ST-BDDVDRW_CH12NS40-INTM-N000700-212003230952
hp_HLDS-BDRE_BU40N-BW42-P000100-211711291655

From:
<https://g6r.de/dw/> - **g6r**

Permanent link:
<https://g6r.de/dw/libredriveio?rev=1773306384>

Last update: **2026-03-12 10:06**

